



Horizontal Stabilizer


2020-04-15




Checking the alignment with a laser




ve
l
af
te
r
pu
tt
in
g
th
e
sk
in
on
...




from bothe sides



Alignment check without skin





Conduit for the trim servo cable



Initial testfit of the skin. I realized that both hs-rib-1 in the middle were mounted backwards and had to drill them out. But no problem to reach the rivets and mount the ribs correctly.



HS riveted







parts primed in my paint booth






Set the first clecos



Using my paint booth for the first time



These are the first rivets I set in my life...



Dimple the empennage skins and clean the holes with a 3.3mm drill.



Ready for priming. Not the most interesting work to clean and deburr the parts...



Rattle can primer applied..



Rewarding to set some rivets after all the prep-work.

